


TECHNICAL DATA

Fluke BCR Zero ohm Calibration Resistor



Product overview: Fluke BCR Zero ohm Calibration Resistor

Zero ohm calibration resistor for Fluke 500 Series Battery Analyzers for performing automated zero calibrations for all function ranges. A zero calibration is required each time a test probe is replaced.

Ordering information



Fluke BCR

Zero ohm Calibration Resistor

Fluke. *Keeping your world up and running.®*

Fluke (UK) Ltd.
52 Hurricane Way
Norwich, Norfolk
NR6 6JB
United Kingdom
Tel.: +44 (0)20 7942 0708
E-mail: cs.uk@fluke.com
www.fluke.com

©2021 Fluke Corporation. All rights reserved.
Data subject to alteration without notice.
11/2021

**Modification of this document is not permitted
without written permission from Fluke Corporation.**