


TECHNICAL DATA

# Fluke BCR Zero ohm Calibration Resistor



## Product overview: Fluke BCR Zero ohm Calibration Resistor

Zero ohm calibration resistor for Fluke 500 Series Battery Analyzers for performing automated zero calibrations for all function ranges. A zero calibration is required each time a test probe is replaced.

## Ordering information



### **Fluke BCR**

Zero ohm Calibration Resistor

---



**Fluke.** *Keeping your world up and running.®*

**Fluke Corporation**  
PO Box 9090, Everett, WA 98206 U.S.A.

**For more information call:**  
In the U.S.A. (800) 443-5853  
In Canada (800) 36-FLUKE  
From other countries +1 (425) 446-5500  
[www.fluke.com](http://www.fluke.com)

©2021 Fluke Corporation.  
Specifications subject to change without notice.  
12/2021

**Modification of this document is not permitted  
without written permission from Fluke Corporation.**