

Data teknis

# Fluke RS200 Probe-Accessories Replacement Set



## Fitur utama

Compatible with PM8918, VPS100, VPS101, VPS121 and VPS200-series probes.

## Ikhtisar Produk: Fluke RS200 Probe-Accessories Replacement Set

Contains replacement parts for usage with the VPS200 & PM8918 Scope Probes.

- Set includes 600V CAT III / 1000V CAT II rated:
  - Hook Clip for Probe Tip (2 Red, 1 Gray)
  - 4-mm Test Probe for Probe (1 Red, 1 Gray)
  - Ground Lead with Hook Clip (1 Red, 1 Gray)
  - Ground Lead with Mini Alligator (2 Black).
  - Ground Spring for Probe Tip (5x) 30V CAT II Rated
- Max. Input Voltage: 600V CAT III, 1000V CAT II per IEC 1010-2-031
- Max. Voltage to Ground: 600V CAT III, 1000V CAT II per IEC 1010-2-031

Compatible with PM8918, VPS100, VPS101, VPS121 and VPS200-series probes.

## Model



### Fluke RS200

ul>

- Set includes 600V CAT III / 1000V CAT II rated:
  - Hook Clip for Probe Tip (2 Red, 1 Gray)
  - 4-mm Test Probe for Probe (1 Red, 1 Gray)
  - Ground Lead with Hook Clip (1 Red, 1 Gray)
  - Ground Lead with Mini Alligator (2 Black).
  - Ground Spring for Probe Tip (5x) 30V CAT II Rated
- Max. Input Voltage: 600V CAT III, 1000V CAT II per IEC 1010-2-031
- Max. Voltage to Ground: 600V CAT III, 1000V CAT II per IEC 1010-2-031

**Fluke.** *Memastikan aktivitas Anda terus berjalan dan beroperasi.*

**Fluke Corporation**

PO Box 9090, Everett, WA 98206 U.S.A.

**For more information call:**

In the U.S.A. (800) 443-5853

In Europe/M-East/Africa

+31 (0)40 267 5100

In Canada (800)-36-FLUKE

From other countries +1 (425) 446-5500

[www.fluke.com](http://www.fluke.com)

**BUT. FLUKE SOUTH EAST ASIA PTE LTD**

Menera Satu Sentra Kelapa Gading #06-05

Jl. Bulevar Kelapa Gading Kav. LA# No. 1

Summarecon Kelapa Gading

Jakarta Utara 14240

Indonesia

Tel: +62 21 2938 5922

Email: [info.asean@fluke.com](mailto:info.asean@fluke.com)

[www.fluke.com/id](http://www.fluke.com/id)

©2021 Fluke Corporation. Specifications subject to change without notice.

11/2021

**Modification of this document is not permitted without written permission from Fluke Corporation.**